

CASE-STUDY: How a Bad Transmission Install Was Resolved With Expert Part Matching

Client Success Story – Used Transmission For Sale



Scan the QR Code

Client Overview

Client Name: Jason Miller


Location: Phoenix, Arizona

Vehicle: 2014 Nissan Altima

Displacement: 2.5L

Issue: Failed transmission replacement from a previous supplier

Jason is a self-employed and works as a HVAC technician. He completely relies on his Nissan Altima to visit his daily clients. After his vehicle's transmission failed, he sourced a used replacement from a local salvaged yard but the unit wasn't VIN-matched and was incompatible with his vehicle's Transmission Control Module which leads to severe performance issues.





The Challenge Faced by Jason

Jason faced a costly and time-consuming setback:

- ◆ **Wrong Part Installed:** The salvage yard supplied a transmission with a mismatched code, causing gear slipping and checks engine lights.
- ◆ **Extra Labor Costs:** His mechanic had to remove and reinstall the unit twice, increasing the repair bill.
- ◆ **Loss of Work Hours:** Jason had to rent a vehicle for several days, affecting his income.
- ◆ **No Support from Original Supplier:** The salvage yard refused a return, citing “no warranty on electronic compatibility.”

“I thought I was saving money by buying local, but it turned into a bigger headache and expense than the original repair.”— Jason Miller



Solution by Used Transmission for Sale


After contacting Used Transmission for Sale, Jason’s problem was addressed through our expert part matching process.

Steps Taken:

- ◆ **VIN-Based Search:** We ran Jason’s full VIN through our nationwide database to identify the exact transmission code and compatibility requirements.
- ◆ **Supplier Verification:** Located a low-mileage, OEM-tested Jatco CVT transmission with matching code RE0F10D from a verified supplier.
- ◆ **Pre-Shipment Testing:** Conducted pressure tests, visual inspections, and verified TCM compatibility before shipping.
- ◆ **Fast Shipping:** Arranged expedited freight delivery directly to Jason’s mechanic in less than 48 hours.
- ◆ **Technical Support:** Provided installation guidelines to avoid repeat issues and ensure proper programming.

How Our Solution Helped Jason

- ◆ **Correct Part First Time:** VIN-matched transmission ensured perfect fit and function.
- ◆ **Reduced Downtime:** Jason's vehicle was back on the road within 3 days of contacting us.
- ◆ **No Additional Labor Loss:** Mechanic installed successfully on the first attempt.
- ◆ **Peace of Mind:** Backed by up to 12-month parts warranty.



Client Testimonial



Jason Miller


Texas



‘They matched my transmission perfectly. No guessing, no rework. I wish I had gone to them first’.

The Impact of Our Solution


- ◆ Downtime Reduced by 60% compared to his previous repair experience
- ◆ Saved \$850 in extra labor and rental costs
- ◆ Zero Post-Install Issues after 3 months of driving
- ◆ Full Restoration of Performance, including smooth shifting and no warning lights



Conclusion

Used Transmission for Sale's expert part matching service transformed Jason's failed repair into a successful, long-lasting fix. By focusing on VIN-based compatibility and pre-shipment quality checks, we eliminated guesswork and costly do-overs proving that the right match is everything when it comes to transmission replacements.





used transmission
strong gears to drive more

Thank You!

For Choosing Our Products

www.usedtransmission.forsale



 info@usedtransmission.forsale